

# UNEVEN BRAKE WEAR PAD PROFILE CHART

Uneven friction wear attributed to worn, corroded or defective brake hardware reduces the life of the pad.

